

ENERGY STAR[®] Progress & Goals Report

96

Lincoln Street

Primary Property Type: K-12 School Gross Floor Area (ft²): 73,400

Built: 2008

For Year Ending: February 28, 2018 Date Generated: April 18, 2018 Property Address: Lincoln Street 801 NE Lincoln St.

Hillsboro, Oregon 97124

Property ID: 1813346

ENERGY STAR® Score¹

1. The ENERGY STAR score is a 1-100 assessment of a building's energy efficiency as compared with similar buildings nationwide, adjusting for climate and business activity.

Performance Comparison						
		Progress			Performance Goals	•
	Baseline (Ending Date 11/30/2010)	(Ending Date 2/28/2018)	% Change	Property's Target	National Median	ENERGY STAR Score of 75
ENERGY STAR Score	90	96	-7	75	50	75
Energy						
Site EUI (kBtu/ft²)	46.4	37.3	-19.6	56.2	71.8	56.2
Source EUI (kBtu/ft²)	99.3	86.6	-12.8	130.5	166.9	130.5
Energy Cost (\$)	63,300.05	60,056.54	-5.12	90,500.29	115,726.2	90,500.29
Energy Cost Intensity (\$/ft²) Greenhouse Gas	0.86	0.82	-5.12	1.23	1.58	1.23
Emissions						
Total GHG Emissions (Metric Tons CO2e)	302.2	259.2	-14.23	390.6	499.4	390.6
Total GHG Emissions Intensity (kgCO2e/ft²)	4.1	3.5	-14.23	5.3	6.8	5.3
Water						
All Water Use (kgal)	1,281.4	N/A	N/A	*	*	*
Indoor Water Use (kgal)	1,281.4	N/A	N/A	*	*	*
Indoor Water Use Intensity (gal/ft²)	17.46	N/A	N/A	*	*	*
Total Water Cost (\$)	16,911.51	N/A	N/A	*	*	*

^{*}Setting and managing water targets is not yet available in Portfolio Manager.