

ENERGY STAR[®] Progress & Goals Report

82

Minter Bridge

Primary Property Type: K-12 School Gross Floor Area (ft²): 50,859

Built: 1980

For Year Ending: February 28, 2018 Date Generated: April 18, 2018 Property Address: Minter Bridge 1750 SE Jacquelin Dr.

Hillsboro, Oregon 97123 **Property ID**: 1813348

ENERGY STAR®
Score¹

1. The ENERGY STAR score is a 1-100 assessment of a building's energy efficiency as compared with similar buildings nationwide, adjusting for climate and business activity.

Performance Comparison						
		Progress			Performance Goals	
	Baseline (Ending Date 11/30/2010)	(Ending Date 2/28/2018)	% Change	Property's Target	National Median	ENERGY STAR Score of 75
ENERGY STAR Score	54	82	-52	75	50	75
Energy						
Site EUI (kBtu/ft²)	43.9	33.6	-23.3	37	47.3	37
Source EUI (kBtu/ft²)	137.7	105.6	-23.3	116	148.4	116
Energy Cost (\$)	58,929.21	51,409.76	-12.76	56,469.76	72,210.09	56,469.76
Energy Cost Intensity (\$/ft²) Greenhouse Gas	1.16	1.01	-12.76	1.11	1.42	1.11
Emissions						
Total GHG Emissions (Metric Tons CO2e)	270.8	207.8	-23.26	228.2	291.8	228.2
Total GHG Emissions Intensity (kgCO2e/ft²)	5.3	4.1	-23.26	4.5	5.7	4.5
Water						
All Water Use (kgal)	556.1	N/A	N/A	*	*	*
Indoor Water Use (kgal)	556.1	N/A	N/A	*	*	*
Indoor Water Use Intensity (gal/ft²)	10.93	N/A	N/A	*	*	*
Total Water Cost (\$)	11.600.46	N/A	N/A	*	*	*

^{*}Setting and managing water targets is not yet available in Portfolio Manager.